

# FACILITY DISCREPANCY REPORT

LOCATION: *ALAKAKET*

DATE: *10/2/18*

- 1. 2 BUCKETS OILY WATER BY TANK 5 - 1 HAS A FILTER IN IT.*
- 2. FUEL SEEPAGE ON INLET SIDE OF CHECK VALVE ON TOP OF TANK 5.*
- 3. TANK 1 - THREADED COUPLING ON LINE LABELED VENT LEAKING - ANDY AND I TIGHTENED IT WITH 2 PIPE WRENCHES - LOOKS LIKE WE STOPPED THE LEAK.*
- 4. ABOUT 3/8" OF FUEL IN BOTTOM OF TRANSFER BOX IN MAIN TANK FARM.*

Completed by: *TOM FERRELL*



**FRONTIER**  
FUEL SERVICE, LLC