

FACILITY DISCREPANCY REPORT

LOCATION: HUGHES

DATE: 9/29/18/9/30/18

1. SOME PIPING, FLANGES & FITTINGS BY TANK 4 NEEDS TO BE REPAINTED.
2. TANK 4 VENT IS MISSING SCREENS.
3. 3" PIPELINE FROM MARINE HEADER TO TANK FARM NEEDS TO BE REPAINTED.
4. 3" PIPELINE NEEDS TO BE SECURED/SUPPORTED BETTER AT MARINE HEADER.
5. WEEDS & VEGETATION NEED TO BE CLEARED FROM AROUND PIPELINE FROM MARINE HEADER TO TANK FARM.

Completed by: Tom Fearrell



FRONTIER
FUEL SERVICE, LLC