



RAFSS Discrepancy Report

(Write in client needs on-site)

- Location: Allakaket
- Date: 2/12/16

* Fire extinguishers in the tank farm
and day tank expired 2012 need (3)

* Flex hose on tank at boiler room
very stressed. Jacked up pipe,
blocked and fixed.

* Flex hose stressed inside tank
farm, may need to be replaced
this summer and re-supported.

* Electrical fixture box has no
cover, wires exposed (location: tank farm)

* Need one tube of water paste

• RAFS Technician Signature: *Paul Campbell*