

FACILITY DISCREPANCY REPORT

LOCATION: Allakaket

DATE: 11/17/17

* Tank #4 1,000K tank next to Water building at some point in past years the interstice was accidentally filled with fuel. We pumped this out last year. The tank still has some remaining fuel in the bottom. Fix: We need a hand piston pump with hose or stinger to slowly pump out the remaining fuel.

* Brush needs trimmed

Completed by:



FRONTIER
FUEL SERVICE, LLC