

Rural Alaska Fuels, Inc.
Fuel Facility Section

Location name: Alakake

Date: 3/31/14

Instructions: This section reports to be completed the first Thursday of every month. Covered inspection forms returned to RAFC Anchorage the next Friday. Do not draw a thorough multiphase or ship any actions. Inspection reports must be signed the bottom of the last page.

	YES	NO	COMPLECTIONS REQUIRED?
1 Are all lvs secured and locked?		<input checked="" type="checkbox"/>	
2 Are ho-end nozzles in good condition?		<input checked="" type="checkbox"/>	
3 Is blending equipment? (Check tag, not current, workbooks)	<input checked="" type="checkbox"/>		In soil prep equipment
OTB: Pipelization connect the day tanks at the tank farm. (See Diagram)			
4 Is the good adjacent to the pipe free of any indication of a deteriorated soil?	<input checked="" type="checkbox"/>		no p. live
5 Is the p. free of any indications of corrosion?			
6 Are all lvs secured and locked?			
7 Are drag pads greas?			
8 Are the connections secure and there no indication of leaks?			
9 Are pipe well supported, with no evidence of being under stress?			
10 Are "N" marking/Vent/Oven lights" and "ADBC placard" visible at all times?			
11 Are these locked?		<input checked="" type="checkbox"/>	None
OTB: This section is to be completed while walking the length of the containment.			
12 Is the fire intact?	<input checked="" type="checkbox"/>		
13 Does the side of the face have "No Smoking/Victims/Op; lighter" sign?			No sigs
14 Is the boundary containment dike in good condition? (Stratified, not leaning or low)			N/A
15 Debris/Debrisive vegetation (H/M) (Med) (Low) Circle one			N/A much snow
16 Brn/white/black (High Med) (Low) Circle one			N/A
17 Check many evidences of liner failure (good order) (allure) Circle one			
18 Is the area free of spill or leaked mater? (Standing liquid)	<input checked="" type="checkbox"/>		Small
19 Is the area free of standing water?	<input checked="" type="checkbox"/>		
20 Is the yr free of all holes, misalignments, etc?	<input checked="" type="checkbox"/>		
OTB: Frying Skin to be completed while inspecting the unleadcank farm. (See Diagram)			
21 Is the end adjacent to the pipe free of any indication of contaminated soil?			
22 Is the p. free of any indications of corrosion?			
23 Are all lvs secured and locked?			NO cleaned FRS
24 Are drag pads present?			
25 Are dam connections secure and there no indication of leak?			
26 Are pipe well supported, with no evidence of being under stress?			
Standard Tanks			
27 Is the tank exterior in good condition and free of any indications of exterior shell?			N/A
28 Is the tank free of any indications of corrosion or shell degradation?			

	YES	NO	COMMENTS/ACTIONS REQUIRED
29 Is the tank foundation in good condt?	<input checked="" type="checkbox"/>		
30 Is the paint on the tank in good condt?	<input checked="" type="checkbox"/>		
31 Is the product ID visible? (One ch side of the tank)			NA/A
32 Is the confined space placed vis?			
33 Are all valves secured and locked?			
N/E: This section pertains to the roof of tank.			
34 Are the tank accessories and man roof condition?			
35 Is the confined space placed vis. Top?			
36 Is the "Safe Exit Limit" written on the tank?			
Lid Tanks			
37 Is the tank exterior in good condition free of any indications of exterior shell leaks?			
38 Is the tank free of any indication of corrosion or shell erosion?	<input checked="" type="checkbox"/>		
39 Is the tank foundation in good condt?	<input checked="" type="checkbox"/>		
40 Is the paint on the tank in good condt?	<input checked="" type="checkbox"/>		
41 Is the product ID visible? (One ch side of the tank)			
42 Is the confined space placed vis?			
43 Are all valves secured and locked?			
N/E: This section pertains to the roof of tank.			
44 Are the tank accessories and man roof condition?	<input checked="" type="checkbox"/>		
45 Is the confined space placed vis. Top?			
46 Is the "Safe Exit Limit" written on the tank?			
N/E: This section pertains to the roof of tank.			
47 Are State, Federal and OSHA prominently displayed?			
48 Are fire extinguishers in good condt and required?	<input checked="" type="checkbox"/>		NO DUSTERS IN SHI RESERVE EQUIPMENT
49 Is the "AD5" placard and no sig signs visible?	<input checked="" type="checkbox"/>		NO SIGNS
50 Is there a copy of the Facility Rese Plan available?	<input checked="" type="checkbox"/>		
51 Is the container locked and secured?	<input checked="" type="checkbox"/>		
N/E:			
Writing inspectors make note of appliances in any the above mentioned that report them immediately to yrdanager and faxcopy to RARS Operational in charge. (907) 383-0436 or FAX 1-7-882-0436			
Inspected by: WY/RE FSE S			
Date: 03/31/14			
Additional Notes:			